

PEMBANGUNAN PIPA TRANSMISI GAS BUMI CIREBON-SEMARANG TAHAP 2 (RUAS BATANG – CIREBON – KANDANG HAUR TIMUR)

No Laporan : PMRK-EPC-00-HSE-FO-PRD-0003		Hari : Rabu		HSE Incharge 1. Yakub	
Area : ALL AREA		Tanggal : February 12, 2025			
POS :		☒ CERAH ☐ MENDUNG ☐ HUJAN			
				Pukul : 7.30	
				Tool Box Meeting ☒ Ok ☐ No	
				Keterangan	
SAFE WORK DAY : 3 Day		STOP CARD : 0 Unsafe: 0		Safe : 0	

No.	Man Power	Person Qty	Man Hours Today	Prev Man Hours Cumm	Total Man Hours	No.	Construction Equipment	Unit	Qty.	Description	QTY		
											Prev	Today	Cumm
A Indirect Manpower													
1	Project Manager	1	8	11	19	1	Total Station	Unit	0	General Safety Talk/Toolbox Meeting	2	1	3
						2	Mobil Operasional	Unit	0	HSE Induction	14	0	14
						3	Pick up	Unit	0	HSE Meeting	1	1	2
						4	Welding Truck	Unit	0	HSE Training	0	0	0
						5	Dolly Truck	Unit	0	Drill	0	0	0
						6	Dump Truck	Unit	0	Safety Patrol	0	0	0
						7	Trailer	Unit	0	Walk Trough	0	0	0
						8	Self Loader	Unit	0	Site Inspection/Site Visit	0	0	0
						9	Rough Tower Crane	Unit	0	HSE Audit	0	0	0
						10	Excavator	Unit	0	Safety Alert	0	0	0
						11	Welding Machine	Unit	0	Equipment/Tools Inspection	0	0	0
						12	Grinding Tools	Unit	0	Meeting Koordinasi	0	0	0
						13	Coating Tools	Unit	0	SIKA/ISA	3	0	3
						14	Holiday Detector	Unit	0	Safety Award	0	0	0
						15	Temperature Gun	Unit	0	Warning Letter	0	0	0
						16	Compressor	Unit	0	Hazardous Waste	0	0	0
						17	Genset	Unit	0	Non Hazardous Waste	0	0	0
						18	Stamper	Unit	0				
						19	Water Pump	Unit	0				
						20	Motorcycle	Unit	0				
B Direct Manpower													
1	Supervisor	1	8	11	19	21	HDD unit	Unit	0				
2	QA/QC	1	8	11	19	22	Auger Boring unit	Unit	0	Fatality	0	0	0
3	HSE Officer	1	8	11	19	23	Hydrotest unit	Unit	0	Lost Time Incident (LTI.s)	0	0	0
4	Paramedic	1	8	11	19	24	Fuel Tank	Unit	0	Day Lost	0	0	0
5	Foreman	2	8	11	19	25	Side Boom	Unit	0	Lost Time Injury(LTI)	0	0	0
6	Teknisi	1	8	22	38	26	Gas Detector	Unit	0	First Aid Case (FAC)	0	0	0
7	Helper	3	8	11	19	27	Light Truck	Unit	0	Severty Rate (SR)	0	0	0
8						28	Crane Truck	Unit	0	Frequency Rate (FR)	0	0	0
9						29	Bulldozer	Unit	0	Environmental Damage	0	0	0
10						30	Compactor	Unit	0	Property Damage (PD)	0	0	0
11						31	Vacum Truck	Unit	0	Motor Vehicle Accident (MVA)	0	0	0
12						32	Shackle	Unit	0	Fire Incident/Explosion	0	0	0
13						33	Lifting Gear	Unit	0	Security Case	0	0	0
14						34	Pipe Clamp	Unit	0	Villager Complaint	0	0	0
15						35	Lampu	Unit	0	Media Attention	0	0	0
16						36	Sorbent Boom	Unit	0	Near Miss	0	0	0
17						37	Cutter Concrete	Unit	0				
18						38	Backhoe Loader	Unit	0				
19						39	Cold Bending	Unit	0				
20						40	Foco Truck 8 Ton	Unit	0				
21						41	Inverter Welder	Unit	0				
22						42	Lever Block	Unit	0				
Total		11	64	121	209								

NO	AKTIVITAS HARI INI	LOKASI	NO	RENCANA BESOK	LOKASI
1	DCU	KP 282+200	1	DCU	KP 282+200
2	TBM		2	TBM	
3	Boring Manual		4	Boring Manual	



PREPARED BY Tanda tangan:  Nama : Yakub Posisi : HSE Officer Perusahaan : PT.Pasopati Reka Daya		ACKNOWLEDGE BY Tanda tangan:  Nama : Posisi : HSE Dept KSO Perusahaan : PT. KSO Timas Pratiwi	
--	--	---	--



FOTO KEGIATAN PROYEK



PEMBANGUNAN PIPA TRANSMISI GAS BUMI CIREBON-SEMARANG TAHAP 2 (RUAS BATANG – CIREBON – KANDANG HAUR TIMUR)




Judul Foto DCU
Tanggal 12 Februari 2025
Loc Mess Pekerja

1

Judul Foto TBM
Tanggal 12 Februari 2025
Loc Mess Pekerja

2



Judul Foto Boring Manual
Tanggal 12 Februari 2025
Loc KP 282+200

3



Judul Foto Boring Manual
Tanggal 12 Februari 2025
Loc KP 282+200

4



Judul Foto Pengukuran kedalam lubang
Tanggal 12 Februari 2025
Loc KP 282+200

5



Judul Foto Merapikan Peralatn Safety Management Traffic
Tanggal 12 Februari 2025
Loc KP 282+200

6